



Meander 3 BEFORE - meander was truncated and filled to create a corral area



Meander 3 AFTER - Restored meander constructed using encapsulated soil/sod lifts on cobble toe, interplanted with live willow stems. A temporary irrigation system was used to help summer grown-in period.



Meander 1 - Existing channel showing eroding bank in straightened reach. This area will be rehabilitated in final phase of Jackknife restoration.

GILLILAN ASSOCIATES, INC.



February 2007

Jackknife Creek  
Stream Restoration Project  
Jackknife Creek Ranch, LLC

Project Overview